

# PF2190 – DirectFlo™ DF1200 / PowerFlo® PF2000 Tune-up Parts Kit

Establishing and following a regularly scheduled maintenance program on your equipment reduces costly downtime and increases productivity. Enclosed you will find the parts required to perform a routine tune-up on your DirectFlo™ or PowerFlo® production blaster. Should you have any questions about performing your own maintenance give our Technical Support department a call at 1-800-796-6626.



MB1455 – Connector with Quicknut (1)



PF2040 – Modulator Housing Assembly (1)



PF2090 – Nozzle Nose (1)



PF2177 – 3/8T-3/8T Union (1)



PF2179 – 3/8T-1/4P Male Connector (1)



ST4014 – 1/4T Bulkhead Union (1) with MB1483 Quicknuts installed



ST4015 – 1/4T Brass Tee (1) with MB1483 Quicknuts installed



MB1233 – 1/4" Abrasive Tube (6 feet)



ST4161 – 1/4T x 1/4P Elbow (1) with MB1483 Quicknut installed




PF2083 – Abrasive Tube (8 feet)




ST5023 – O-ring (1) (1.734ID x .139THK)



ST5495 – O-ring (1) (5.859ID x .139THK)



TS302 – Modulator Housing Assembly Replacement Instructions (1)



TS305 – DF/PF Tune-Up Kit Instructions (1)



ST5496 – O-ring (1) (.296ID x .139THK)



ST5504 – O-ring (1) (.359ID x .139THK)

Want to get the most from your production quality micro-abrasive blaster? You can review technical bulletins on everything from modulator maintenance to the importance of clean, dry air, or access Comco's complete library of documents on specific micro-abrasive blasting applications. Download this informative literature—and more—directly from our website at [www.COMCOinc.com](http://www.COMCOinc.com), or call Customer Service today!

Comco Inc. 2151 N. Lincoln Street / Burbank CA 91504-3344, USA / 818-841-5500  
E-mail: [tech@COMCOinc.com](mailto:tech@COMCOinc.com) / Fax: 818-955-8365 / [www.COMCOinc.com](http://www.COMCOinc.com)

PF2190PL

**COMCO INC.**  
(800) 796-6626