

PF2190 – DirectFlo/PowerFlo Tune-Up Parts Kit

Establishing and following a regularly scheduled maintenance program on your equipment reduces costly downtime and increases productivity. Enclosed you will find the parts required to perform a routine Tune-Up on your DirectFlo or PowerFlo production blaster. Should you have any questions about performing your own maintenance give our Technical Support department a call at 1-800-796-6626, ext. 127.



MB1455 – Hose Connector with Quicknut (1)



PF2040 – Modulator Housing Assembly (1)



PF2090 – Nozzle Nose Assembly (1)



PF2177 – 3/8T-3/8T Union (1)



PF2179 – 3/8T-1/4P Male Connector (1)



ST4014 – 1/4T Union Bulkhead (1)



ST4015 – 1/4T Brass Tee (1)



MB1233 – 1/4" Abrasive Tube (6 feet)



ST4161 – 1/4T x 1/4P Elbow (1)




PF2083 – 3/8" Abrasive Tube (8 feet)




ST5023 – O-ring (1)
(1.734ID x .139THK)



ST5495 – O-ring (1)
(5.859ID x .139THK)



TS302 – Modulator Housing Assembly Replacement Instructions (1)



TS305 – DF/PF Tune-Up Kit Instructions (1)



ST5496 – O-ring (1)
(.296ID x .139THK)



ST5504 – O-ring (1)
(.359ID x .139THK)

Want to get the most from your production quality micro-abrasive blaster? You can review technical bulletins on everything from modulator maintenance to the importance of clean, dry air, or access Comco's complete library of documents on specific micro-abrasive blasting applications. Download this informative literature—and more—directly from our website at www.COMCOinc.com, or call Customer Service at extension 130 today!

Comco Inc. 2151 N. Lincoln Street / Burbank CA 91504-3344, USA / 818-841-5500
E-mail: tech@COMCOinc.com / Fax: 818-955-8365 / www.COMCOinc.com

PF2190PL

COMCO INC.
(800) 796-6626