

PF2489 – DirectFlo™ DF1400 / PowerFlo® PF2400 Tune-up Parts Kit

Establishing and following a regularly scheduled maintenance program on your equipment reduces costly downtime and increases productivity. Enclosed you will find the parts required to perform a routine tune-up on your DirectFlo™ or PowerFlo® production blaster. Should you have any questions about performing your own maintenance give our Technical Support department a call at 1-800-796-6626.



MB1455 – Connector with Quicknut (2)



PF2040 – Modulator Housing Assembly (1)



MB1483 – Quicknut (1)



PF2189-2 – PowderGate Valve Seat Assembly (1)



MB1653 – PowderGate Nose (1)



ST4014 – 1/4" T Bulkhead Union (1) with MB1483 Quicknuts installed




ST4209 – 3/8" Tubing Ferrule Set (3)



MB1233 – 1/4" Abrasive Tube (6 feet)



ST4184 – 3/8" T x 1/4 - NPT Male Connector (1)



PF2139 – O-Ring Replacement Kit



PF2083 – 3/8" Abrasive Tube (8 feet)



TS309 – DF/PF Tune-up Kit Instructions (1)

Want to get the most from your production quality micro-abrasive blaster? You can review technical bulletins on everything from modulator maintenance to the importance of clean, dry air, or access Comco's complete library of documents on specific micro-abrasive blasting applications. Download this informative literature—and more—directly from our website at www.COMCOinc.com, or call Customer Service today!

Comco Inc. 2151 N. Lincoln Street / Burbank CA 91504-3344, USA / 818-841-5500

E-mail: tech@COMCOinc.com / Fax: 818-955-8365 / www.COMCOinc.com

PF2489PL

COMCO INC.
(800) 796-6626